


Case study


Improving PCBA Yield


Subrat Prajapati


Title: Improve the Yield of P	CBA from 82% to	92% at PCBA functiona	al Test Stage.
Current situation: Presen Sigma	•		
Scope of Project: Vendor	PCB Assembly to F	unctional Testing of PCBA	
Characteristics	Measure	Defect Definition	
Yield at PCBA functional testing	Percentage	Yield < 92%	
Project Black Belt: Subrat Praja	apati		



SIPOC Diagram









Pareto Chart

Defects at Test Jig stage related to Solderibility has been transformed to Pareto as below-






Solder short in IC leads

NEED	DRIVERS	CTQs	DEFECT DEFINITION	MEASURE FOR DEFECT	KANO STATUS
Reduce Solderibility Defect in PCBA	Reflow process	Good Solderibility As per IPC610	Any incidence solder short in Soldering of SMD component	No.of solder short after reflow In Video microscope inspection	Less the Better
	Screen Printing Process	Paste thickness Consistency	Any incidence solder short in Soldering of SMD component	No.of solder short after reflow In Video microscope inspection	Less the Better






Data collection plan for			Project		Date	
PCBA Solderibility failures in shop floor		Reduction of Solderibility problem in PCBA		10.10.2009		
I. What is the n	eed of this data c	ollection?	2. Who will collect the data?		3. Location of data collection	
To find out the pr causes	resent status of PC	BA failures & to validate it's	SP		Reflow M/C- Vendor Programming/Testing- Screen printing machine	
	DATA				•	
What	Measure type / data type	How measured	Sampling		Purpose	
Temperature	Continuous	Thermocouple reader Reflow	20 samples	Check I	Process capability	
PCBA Failed	Discrete	At Test Jig stage	100 samples		failure rate before and after nentation of solution	
Solder Paste thickness	Continuous	Manufacturer Machine	30 samples	Paste	Type may be factor in Solderibility	




Vendor Visit




Data Plotting- Solder Paste Height measurement


Measure



Observation : From Normal Distribution Summary shows Mean of Paste thickness observed is 7.8 mil (198 micron).


I-mR/ Paste Thickness






Cpk Analysis of Solder Paste Thickness

Measure




Concludes 80% of process is running outside USL, with Cpk= - 0.24 Mean Paste thickness = 7.8

Paste Thickness running out of Specification




Vital cause



Vital cause identified After Brainstorming

- 1. Present Stencil opening is 1:1 (PCB Pad vs Stencil aperture ratio) leading to excess amount of solder paste deposition, and solder short after reflow.
 - Presently using Solder Paste Type-3 of 25-45 micron granule size, in PCBA having IC of 15 mil pitch. As per 5 ball rule, this can be cut-off point. Decided to use Type-4 (20-38 micron) solder paste in order to get better solder paste transfer efficiency in 15mil pitch IC through DOE



Reduced Aperture width'W' by 5% in IC having Pitch =<20mil, to reduce paste volume on Pad hence reduce chance of solder short after reflow.

Stencil

Desta	TO			Testine
Paste	13 VS	14 Hy	pothesis	lesting

Chi-Sq	uare Tes	t: Solde	r Paste T-3 Vs T-4
	Good	Bad	Total
т4	57	15	72
	51.51	20.49	
	0.586	1.472	
тз	36	22	58
	41.49	16.51	
	0.727	1.827	
Total	93	37	130
Chi-Sq 0.032	= 4.61	2, DF =	= 1, P-Value =

P-value shows Solder Paste T3/T4 has effect in Solderibility (solder short) in 15 Mil pitch IC Reflow temperature effect on BGA soldering

Chi-Square	Test:Reflow	Temperature
	Good	Bad
1	56	32 88
	64.60 23	.40
	1.144 3.3	157
2	82	18 100
	73.40 26	.60
	1.007 2.	778
Total	138	50 188
Chi-Sq = 8.086	, DF = 1, P-V	Value = 0.004

P-value shows Reflow Temperature T_{Peak} At 220 & 235 has effect in BGA soldering

Test:

BGA Pull Test conducted as below-Soldered BGA(at Tpeak=220:NonROHS profile) has been pulled up by BGA Rework Station at **190 DegC** (As planned).

Observation:

Found 20% BGA Balls Came out in BGA & remaining 80% BGA Balls remain in Board.

Conclusion:

Good soldering Balls remain on Board after Pull Test. Bad Soldering Balls came out with BGA package. Shows BGA Balls are not melting on Board At 220 DegC.

BGA manufacturer recommends 235 Peak Body Temperature, will not be suitable to my PCBA having non-ROHS parts.


pulled 20% Balls 80% Balls **Board-PCBA** Balls **BGA Pull out BGA** Pic for ref BGA Board

Reflow process Reflow Profile running at Vendor – [RTS – Ramp to Spike Profile] General Description Optimization Fri Nov 02 2007 16:58:05 **Present Profile** PWB-MB PMS 26 CS (TEST-PROFILE) 200 150 Celsius 100 Z3 Z4 Z5 Z6 Z7 Z8 Z9 Z2 Z1 Original 50 100 150 200 250 Predicted 0 49 98 197 246 147 Time Seconds ACTING T Above RTS Profile to be Looked at for stable soldering of PCBA as well as BGA(ROHS Device) soldering in Non-ROHS environment.


Improve

Effect	Cause	Solution	Implementation Risk		Risk Closed	Responsibility
	Screen printing Paste Thickness variation	Machine Parameters Optimized	Solder short may increase	To be run in Pilot lot of 30 no PCBA for monitoring	Parameters Freeze	Machine Supervis
Solder Short		Cleaning of ON-line Stencil reduced from 10 PCBA to 5 PCBA	Cycle time can increase	Cycle time to be monitored	Cycle time no change as Pick- place machine is having high cycle time than screen printing	Machine operator
		Measurement of Paste Thickness Process Deployed	No Risk	No Risk	System Deployed	Quality Manager
		Stencil Initiated with 5% reduction in aperture width in order to reduce paste Volume in IC<20mil pitch	May induce less solder problem	New stencil to be run in Pilot Lot of 30 numbers PCBA before deploying in production lot	Monitoring	Design/ Process Dept -
	Reflow Profile	Profile Changed from Ramp to Spike(RTS) to Ramp Soak Spike(RSS) from DOE	RSS may need more fine tuning for good Solderibility	To be monitored	Monitoring	Process Engineering

DOE




Improve




Concludes paste thickness lying outside USL reduces to 13% from 80%, with Cpk= 0.35 from -0.24 Mean Paste thickness = 6.0 from 7.8 mil

Improve



New RSS - Ramp Soak Spike Profile Deployed




Reflow process



Benefit: Due to Soak time it is facilitating flux to get activated which is useful for expired IC, obsolesce IC(As in our case) for getting good Solderibility. BGA checked in X-ray/Video scope


Pilot lot of 150 PCBA run and Quality confirms to IPC 610, class III.

BGA Ball Snaps shows A good wetting o/p from video scope-



Results & Controls

Control




I-mR Chart implemented at Vendor for monitoring of Paste thickness

Results & Controls

FTP 80% We will guide for DPMO calculation for initial lot. Reflow DPMO 5000 Vendor to maintain record & log. Programming / Yield 96% Vendor to maintain records & log.	Quality	Index Matrix			
Screen Printing Control Chart 4.5 to 7 mils. display at measurement area. Reflow FTP 80% We will guide for DPMO calculation for initial lot. Reflow DPMO 5000 We not to maintain record & log. Programming / Yield 96% Vendor to maintain records &	Process		Benchmark	Actions / Responsibility	
Reflow Programming / Yield 96% calculation for initial lot. Vendor to maintain record & Image: Constraint of the second sec	Screen Printing	Control Chart	4.5 to 7 mils.		
Programming / Yield 96% Vendor to maintain records &		FTP	80%	3	
	Reflow	DPMO	5000	DPMO.xis	
lesting display.	Programming / Testing	Yield	96%	Vendor to maintain records & display.	
Main Unit AssemblyYield98%Vendor to maintain records & display.		Yield	98%		

Results



Thank You

Prajapatis@myw.ltindia.com, Subratprajapati@gmail.com